11th November 2014
BJ/SH-L2/166

BSE Limited
Corporate Relationship Department
1st Floor, New Trading Ring
Rotunda Bldg, PJ Towers
Dalal Street, Fort
Mumbai – 400 001.

National Stock Exchange of India Limited
Exchange Plaza, 5th Floor
Plot No. C/1, G Block
Bandra-Kurla Complex
Bandra (East)
Mumbai – 400 051.

Dear Sirs,

Unit-1 of Maithon Power Limited (MPL), a subsidiary of the Company with Damodar Valley Corporation, tripped on Sunday evening due to failure of Y-Phase GT bushing. The porcelain portion ruptured due to the fault and the oil of the bushing caught fire.

Mulsifier system (automatic water sprinkler) operated on auto supported by Fire control team of MPL extinguished the fire. No oil has spilled from the Transformer itself. As a precautionary measure all the drains near to GT were sealed with mud dumping.

The Unit was shut down safely. No casualty or injury is reported. Damage assessment and repair thereof will be carried out by BHEL.

Yours faithfully,
For The Tata Power Company Limited

Company Secretary

Printed on 100 % Recycled Paper