VMS TMT LIMITED

Registered office & Factory :
Survey No. 214, Near Water Tank, Bhayla, Bavla-382220.
Ahmedabad, Gujarat, India
Email : compliance@vmstmt.com • Website : www.vmstmt.com
Mob. 63575 85711 • CIN No.L27204GJ2013PLC074403

Date: 02/11/2026

To, **BSE Limited,** Phiroze Jeejeebhoy Towers, Dalal Street, Mumbai 400001 **Scrip Code:** 544521 **ISIN:** INE0SJA01013	To, **National Stock Exchange of India Limited** Exchange Plaza, Bandra Kurla Complex, Bandra (E), Mumbai-400 051 **Security Symbol:** VMSTMT

Sub : Intimation regarding Furnace breakdown and temporary suspension of operations at the Company's manufacturing facility.

Ref : Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("the Regulations")

Dear Sir/ Madam,

Pursuant to Regulation 30 of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015, as amended, we hereby inform you that on Friday, October 30, 2026 there was a technical malfunction in the furnace system led to a breakdown of the Company's 16 MW / 30 MT Induction Melting Furnace, with leakage of molten metal, resulting in temporary suspension of operations at the manufacturing facility at Survey No. 214, Near Water Tank, Bhayla, Ahmedabad, Bavla, Gujarat, India, 382220

The cause of the incident is under investigation. No injury or loss of life has been reported.

Based on the preliminary assessment, the leakage of molten metal has caused considerable damage to the copper coil and other critical components of the furnace. The associated transformer also appears to have sustained damage, the extent of which is yet to be ascertained. The Company is undertaking a detailed technical assessment to evaluate the damage to the furnace and associated equipment, including the transformer, and to determine the repair and restoration required.

We also confirm that the factory is adequately insured, and the Insurance Company has been duly informed.

The Company is taking all necessary steps to initiate the requisite repair and restoration activities at the earliest. However, considering the preliminary assessment of the damage, the restoration process may take some time, and the exact timeline for resumption of normal operations is presently not ascertainable.

Further updates will be provided in due course.

VMS TMT LIMITED

Registered office & Factory :
Survey No. 214, Near Water Tank, Bhayla, Bavla-382220.
Ahmedabad, Gujarat, India
Email : compliance@vmstmt.com • Website : www.vmstmt.com
Mob. 63575 85711 • CIN No.L27204GJ2013PLC074403

We acknowledge that this intimation is being made beyond the timeline prescribed under Regulation 30. The delay occurred because the Company's management was occupied with emergency response, securing the premises and carrying out the initial assessment. This is the first incident of its kind in the Company's operations, and the delay was unintentional.

We request the Exchanges to kindly take the above on record and condone the delay.

Thanking You.
Yours faithfully,

For VMS TMT LIMITED

Varun Manojkumar Jain

Digitally signed by Varun Manojkumar Jain

VMS TMT LIMITED

_____

Varun Manojkumar Jain
Managing Director
DIN: 03502561