

Date: August 1, 2018

National Stock Exchange of India Limited
Exchange Plaza
Bandra Kurla Complex
Bandra (East)
Mumbai – 400 051.

Stock Code: GSCLCEMENT

Sub: Disclosure under Regulation 30(3) of SEBI (Listing Obligations and Disclosure Requirements) Regulations 2015 read with policy on determination of materiality of events with regard to restart of Kiln operations.

Dear Sir,

We give below reply to your queries:

1. The Plant was stopped due to heavy rains to avoid any break down in the plant. Such precautionary action is not covered under Insurance. The loss of Clinker production result in lower profitability by Rs.24 lakhs approximately.
2. Expected quantum of loss/damage caused;

The loss of Clinker is 20,000 MT. and loss of profit Rs.24 Lakhs.

This is for your information.

Thanking you

Yours faithfully,
For **GUJARAT SIDHEE CEMENT LIMITED**



V. R. MOHNOT
CFO & CO. SECRETARY