गेल (इंडिया) लिमिटेड
(भारत सरकार का उपक्रम-
महारत्न कम्पनी)
GAIL (India) Limited
(A Government of India Undertaking-
A Maharatna Company)

ND/GAIL/SECTT/2014

December 19, 2014

Listing Department
Bombay Stock Exchange Limited
Floor 1, P.J. Towers, Dalal Street,
Mumbai – 400 001

Dear Sir,

Please find enclosed a copy of Press Releases regarding **"Third party causes minor damage to GAIL's HVJ Pipeline near Ujjain due to borewell drilling - GAIL team responds swiftly – Repair work already started".**

The above is for your information and record please.

Thanking you,

Yours faithfully,

(N.K. Nagpal)
Company Secretary
e-mail: nknagpal@gail.co.in

Encl.: As above

Copy to:

1. Listing Department,
   National Stock Exchange of India Limited
   Exchange Plaza, 5th Floor,
   Plot No C/1, G Block, Bandra-Kurla Complex,
   Bandra (East),
   MUMBAI – 400051

2. Deutsche Bank AG, Filiale Mumbai
   TSS & Global Equity Services
   The Capital, 14th Floor
   C-70, G Block, Bandra Kurla Complex
   Mumbai -400051

GAIL (India) Limited

Third party causes minor damage to GAIL's HVJ Pipeline near Ujjain due to borewell drilling

Leakage detected in pipeline – No fire, no injuries reported

GAIL team responds swiftly – Repair work already started

No impact on natural gas and LPG supply to customers

New Delhi, December 19, 2014. An incident of leakage of natural gas due to third party damage (of minor category) was reported from Hazira – Vijaipur – Jagdishpur (HVJ) pipeline of GAIL (India) Limited near Ujjain (Madhya Pradesh) today morning. There is no case of any injury or fire because of the incident and gas supply to all customers remains unaffected.

The incident occurred early this morning because of third party damage to the pipeline when some persons were trying to drill a borewell near Ujjain – Khera Compressor station of HVJ pipeline system between Kacchibaroda –Makrawana.

The leakage was reported by local patrolling personnel. Immediate action was taken to isolate the affected section of the pipeline and gas is being vented from the section.

There is no impact on Natural Gas and LPG customers because of the incident as supplies are being maintained due to availability of parallel Dahej – Vijaipur (DVPL) – I and II pipelines.

Senior officials and Pipeline Maintenance Team of GAIL have already reached the site. Spares and repair equipment and other resources required for restoration of affected pipeline are being mobilized. The local administration of Ujjain has also been informed.