

MSIL: CSL: NSE: 2013

27th November 2013

The Vice President

National Stock Exchange of India Limited

"Exchange Plaza", Bandra- Kurla Complex

Bandra (E)

Mumbai- 400 051

Sub: Press Release

Dear Sir,

Please find enclosed herewith as annexure "A" a copy of press release being issued today.

Kindly take the same on record.

Thanking you,

Yours truly,

For Maruti Suzuki India Limited



Sanjeev Grover

DGM- Corporate Secretarial

Encl: As above

MARUTI SUZUKI INDIA LIMITED

Registered Office :
Plot No. 1, Nelson Mandela Road,
Vasant Kunj, New Delhi 110070, India
Tel: 011-46781000 Fax: 011-46150275-76

Gurgaon Plant :
Palam Gurgaon Road, Gurgaon 122015
Haryana, India
Tel: 0124-2346721 Fax: 0124-2341304

Manesar Plant :
Plot No. 1, Sector 3A, IMT
Manesar, Gurgaon 122051 Haryana, India
Tel: 0124-4884000 Fax: 0124-4884199

Issued in Customer Interest

Maruti Suzuki to recall 1492 vehicles (Ertiga, Swift, Dzire and A-Star)

New Delhi, November 27, 2013: Maruti Suzuki India Limited today announced that it will inspect the steering column for 1492 vehicles (Ertiga: 306 nos, Swift: 592 nos, Dzire: 581 nos, A-Star: 13 nos), manufactured between 19th October, 2013 and 26th October 2013. If the steering column is found defective, the company will replace the steering column free of cost.

This exercise is limited to vehicles within the above specified range and does not pertain to any other vehicle of the Company or any of its exports.

Maruti Suzuki dealers will contact owners of all vehicles in the above range.

The new steering column has been despatched to dealer workshops.

Users of Maruti Suzuki cars (Ertiga, Swift, Dzire and A-Star) purchased after 19th October, 2013, can check the website www.marutisuzuki.com to ascertain if their car is among the above mentioned vehicles.

The customer is requested to fill in the chassis number (MA3 followed by 14 digit alpha-numeric number) on the computer screen. The chassis number is embossed on the vehicle ID plate and is also in the vehicle invoice / registration documents.

Customers may also contact the nearest Maruti Suzuki dealer workshop to ascertain if their vehicle is among the above vehicles.

Information on this recall hereafter will be also available for customers on the company website: www.marutisuzuki.com

