

MSIL: CSL: NSE&BSE: 2016

19th May 2016

Vice President

National Stock Exchange of India Limited

"Exchange Plaza", Bandra – Kurla Complex

Bandra (E)

Mumbai – 400 051

General Manager

Department of Corporate Services

Bombay Stock Exchange Limited

Phiroze Jeejeebhoy Towers

Dalal Street, Mumbai – 400 001

Sub: Press Release

Dear Sir,

Please find enclosed herewith as Annexure - "A", a copy of press release being issued today.

Kindly take the same on record.

Thanking you,

Yours truly,

For **Maruti Suzuki India Limited**



S. Ravi Aiyar

Executive Director (Legal)

& Company Secretary

Encl.: As above

MARUTI SUZUKI INDIA LIMITED

CIN: L34103DL1981PLC011375

Regd. & Regional Office (North-1):

Maruti Suzuki India Limited,
1 Nelson Mandela Road, Vasant Kunj,
New Delhi 110070, India.

Tel: 011-46781000, Fax: 011-46150291

www.marutisuzuki.com

Gurgaon Plant:

Maruti Suzuki India Limited,
Old Palam Gurgaon Road,
Gurgaon 122015, Haryana, India.

Tel. 0124-2346721, Fax: 0124-2341304

Manesar Plant:

Maruti Suzuki India Limited,
Plot No.1, Phase 3A, IMT Manesar,
Gurgaon 122051, Haryana, India.

Tel: 0124-4884000, Fax: 0124-4884199

Press Release

Issued in Customer Interest

Maruti Suzuki's Service Campaign for S-Cross

New Delhi, May 19th, 2016: Maruti Suzuki India Limited will undertake a Service Campaign to inspect a suspected fault and replace a brake part in 20,427 units of S-Cross. These vehicles were manufactured between April 20th 2015 and February 12th, 2016.

Owners of the impacted vehicles will be contacted by dealers.

Service Campaigns are undertaken globally by automobile companies to rectify faults that may potentially cause inconvenience to customers.

This Service Campaign applies to both the variants of S-Cross (DDiS 200 and DDiS 320).

The inspection and replacement will be done free of cost for the customer.

S-Cross owners can check the NEXA website www.nexaexperience.com to ascertain if their vehicle is impacted.

The customer is requested to fill in the chassis number (MA3 followed by 14 digit alpha-numeric number) on the computer screen. The chassis number is embossed on the vehicle ID plate and is also in the vehicle invoice / registration documents.

Customers may also contact the nearest Maruti Suzuki dealer workshop to ascertain if their vehicle is impacted.