

MSIL: CSL: NSE&BSE: 2016

27th May 2016

Vice President
National Stock Exchange of India Limited
“Exchange Plaza”, Bandra – Kurla Complex
Bandra (E)
Mumbai – 400 051

General Manager
Department of Corporate Services
Bombay Stock Exchange Limited
Phiroze Jeejeebhoy Towers
Dalal Street, Mumbai – 400 001

Sub: Press Release

Dear Sir,


Please find enclosed herewith as Annexure - “A”, a copy of press release being issued today.

Kindly take the same on record.

Thanking you,

Yours truly,

For Maruti Suzuki India Limited


S. Ravi Aiyar

Executive Director (Legal)
& Company Secretary

Encl.: As above

MARUTI SUZUKI INDIA LIMITED

CIN: L34103DL1981PLC011375

Regd. & Regional Office (North-1):
Maruti Suzuki India Limited,
1 Nelson Mandela Road, Vasant Kunj,
New Delhi 110070, India.
Tel: 011-46781000, Fax: 011-46150291
www.marutisuzuki.com

Gurgaon Plant:
Maruti Suzuki India Limited,
Old Palam Gurgaon Road,
Gurgaon 122015, Haryana, India.
Tel. 0124-2346721, Fax: 0124-2341304

Manesar Plant:
Maruti Suzuki India Limited,
Plot No.1, Phase 3A, IMT Manesar,
Gurgaon 122051, Haryana, India.
Tel: 0124-4884000, Fax: 0124-4884199

E-mail: investor@maruti.co.in

PRESS RELEASE

Annexure-“A”

Issued in Customer Interest

Maruti Suzuki to recall 75,419 Baleno cars and 1,961 DZire cars (only AGS variant)

New Delhi, May 27th, 2016: Maruti Suzuki will proactively and voluntarily recall 75,419 Baleno cars (petrol and diesel), manufactured between August 3, 2015 and May 17, 2016 to upgrade the airbag controller software. Of these, 15,995 Baleno cars (only diesel), manufactured between August 3, 2015 and March 22, 2016, will also be attended to for inspection and replacement of a faulty fuel filter.

The Baleno cars covered in the recall include 17,231 units of exports.

In addition, 1,961 DZire Diesel cars (only AGS variant) will be attended to for inspection and replacement of a faulty fuel filter.

Starting 31 May 2016 owners of the vehicles covered will be contacted by Maruti Suzuki dealers. The software upgrade and the replacement of faulty fuel filter, will be done free of cost.

To ascertain if their vehicle is covered, owners may check at www.nexaexperience.com for Baleno and at www.marutisuzuki.com for DZire Diesel (only AGS variant).

The customer is requested to fill in the chassis number (MA3 followed by 14 digit alpha-numeric number) on the computer screen. The chassis number is embossed on the vehicle ID plate and is also in the vehicle invoice/registration documents.