

Ref. No.: BCCL: CS: F-Post-Listing: 169

Dated: 29.05.2026

To,  
Listing Department,  
Bombay Stock Exchange Limited,  
Mumbai-400051  
Scrip Code 54467

To  
Listing Department,  
National Stock Exchange of India Limited  
Mumbai-400051  
Ref: ISIN – INE05XR01022

**Sub: Disclosure under Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements), Regulations 2015- Intimation of Accident at New Benedih Patch of ABOCP Mine of BCCL.**

Dear Sir/Madam,

We regret to inform that an unfortunate accident occurred on May 29, 2026, at about 12:00 noon at the New Benidih Hired Patch of Amalgamated Block-II OCP under Block-II Area of Bharat Coking Coal Limited (BCCL).

As per initial information, due to heavy thunderstorm activity accompanied by lightning and heavy rainfall, the edge of the haul road slid, causing a passing dozer to topple down along with the sliding mass. During the incident, one dozer operator of the contractor sustained fatal injuries.

The matter has been reported to the concerned authorities. Further detailed investigation is being carried out to ascertain the exact cause and circumstances leading to the accident.

Operations at New Benedih Patch have been stopped temporarily. However, other patches of the mine are operating normally.

This is for your information and record please.

**Yours Faithfully,**  
**For Bharat Coking Coal Limited**

**Debanuj Debnath**  
**Company Secretary & Compliance Officer**