



HINDUSTHAN NATIONAL GLASS & INDUSTRIES LTD.

Registered Office : 2, Red Cross Place, Post Box : 2722, Kolkata - 700 001, India

Tel. : 2254 3100, Fax : (91) (33) 2254 3130

E-mail : hngkol@hngil.com, Website : www.hngil.com

CIN - L26109WB1946PLC013294



SEC/SE/445

September 12, 2024

1. The Dy. Manager (Listing)
BSE LIMITED
Phiroze Jeejeebhoy Towers,
Dalal Street, Mumbai 400 001
(Scrip Code: 515145)
2. The Manager, Listing Department
National Stock Exchange of India Ltd.,
Exchange Plaza, Bandra Kurla Complex,
Bandra (E), Mumbai 400 051
(Scrip Code: HINDNATGLS)
3. The Secretary
The Calcutta Stock Exchange Ltd.,
7, Lyons Range, Kolkata-700 001
(Scrip Code: 10018003)

Dear Sir(s)/Madam,

Sub: **Intimation under Regulation 30 of the SEBI (Listing Obligations and Disclosures Requirements) Regulations, 2015 - Glass Leakage Incident at Hindusthan National Glass & Industries Limited at its plant being Furnace No. 6 at Rishra, West Bengal.**

In terms of Regulation 30 of SEBI (Listing Obligations and Disclosures Requirements) Regulations, 2015 ('SEBI LODR Regulations'), we wish to bring to your immediate attention a significant operational incident that has occurred at our Glass manufacturing facility located at Rishra, West Bengal.

Incident Summary:

On 3rd September 2024, at approximately 1:00 AM, a glass leakage incident occurred at Furnace No. 6, at Rishra, West Bengal. The leak occurred at the right-hand side throat gable wall of the Furnace as a result of which the glass level of furnace got reduced. The incident was identified promptly by our on-site operational team, and all necessary emergency protocols were activated to contain the situation. The Company has installed the latest firefighting equipments and was able to contain the damage successfully. However, the production at Furnace 6 has stopped. The Furnace is quite old which is the primary reason for the leakage. We are assessing the full extent of the operational disruption and doing a Root Cause analysis.

The Company is in receipt of a visit report dated September 12, 2024 from a technical expert and as per the said report, the furnace refractories are severely damaged. Even after the planned repairs by the plant, operating the furnace poses potential risks to the safety of the plant. Hence, the operational disruption caused due to closure of Furnace No. 6, may be considered as a material event and thus the Company is making the disclosure as per Regulation 30(4) SEBI LODR Regulations.

**Jit Roy
Choudhury**

Digitally signed by
Jit Roy Choudhury
Date: 2024.09.12
17:29:24 +05'30'



Further, the details as required under Regulation 30 of the SEBI LODR Regulations read with SEBI Circular No. **SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123** dated July 12, 2023, are given below:

Sl No.	Particulars	Details
1.	Expected quantum of loss/damage caused;	No damage reported
2.	Whether loss/damage is covered by insurance or not including the amount;	NA
3.	Estimated impact on the production/operations;	Temporary closure of Furnace No. 6 at Rishra
4.	Factory/unit where the incident took place including reasons	Furnace No. 6, at Rishra Unit, West Bengal

Also, please note that as more information becomes available, we will provide further updates regarding the impact of the incident and the potential implications for our financial performance. We appreciate your understanding and cooperation in this matter. Our priority remains the safety of our employees, the integrity of our operations, and the transparency of our communications with all stakeholders.

Thanking You,

Yours faithfully,

For **Hindusthan National Glass & Industries Limited**

Jit Roy

Choudhury

(Jit Roy Choudhury)

Company Secretary & Compliance Officer

Digitally signed by Jit Roy
Choudhury
Date: 2024.09.12 17:29:49
+05'30'

