

SUNDARAM BRAKE LININGS LIMITED

Padi, Chennai - 600 050, India.



Telephone: 73580 33474

E-mail : sbl@tvssbl.com

Website : www.tvssbrakelinings.com

PAN : AADCS4888E

Sec1/04/Q1/ 2026-27

11th April, 2026

National Stock Exchange of India Limited Exchange Plaza, 5 th Floor Plot No. C/1, "G" Block Bandra Kurla Complex Bandra (East), Mumbai-400 051 Scrip Code: SUNDRMBRAK	BSE Limited Floor 25, P J Towers, Dalal Street, Mumbai – 400 001 Scrip Code: 590072
---	---

Dear Sir/Madam,

Sub: Intimation regarding a fire incident occurred at our Plant I situated at Kariapatti, Virudhunagar, Tamil Nadu.

Ref: Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("Listing Regulations")

Pursuant to Regulation 30 of the Listing Regulations, it is hereby informed that on Friday, 10th April 2026, at around 09:55 P.M. (IST) a fire incident occurred at the factory of our Plant I situated at Kariapatti, Virudhunagar, Tamil Nadu. (The information regarding the said incident was received by the Secretarial Team on 11 April 2026 at 10:00 A.M. (IST))

Impact on Operations:

Fire was controlled within time and fortunately, there were no casualty and injury to life. However, the affected operations will be temporarily shut. The extent of damage to assets and equipment is currently being evaluated, and a detailed estimate will be ascertained in due course.

Insurance Coverage:

We would like to state that the Asset at the affected plant is adequately insured, and the firm has already intimated the insurance company for the incident and insurance survey is expected to be conducted in due course.

Please find enclosed herewith the details as required under Regulation 30 of SEBI (LODR), 2015 read with SEBI Circular No. SEBI/HO/CFD/PoD2/CIR/P/0155 dated 11th November 2024 in Annexure A.

This is for your information and records.

Thanking You

Yours truly,

For Sundaram Brake Linings Limited

Hari S
Chief Financial Officer

MANUFACTURERS OF TVS BRAKE LININGS & CLUTCH FACINGS

Registered Office : Padi, Chennai - 600 050. India.

CIN : L34300TN1974PLC006703

SUNDARAM BRAKE LININGS LIMITED

Padi, Chennai - 600 050, India.



Telephone: 73580 33474

E-mail : sbl@tvssbl.com

Website : www.tvssbrakelinings.com

PAN : AADCS4888E

Annexure A

Sr. no	Particulars	Details
1	Expected quantum of loss /damage caused;	Fire was controlled within time and fortunately, There were no casualty and injury to life. However, the affected operations will be temporarily shut. The extent of damage to assets and equipment is currently being evaluated, and a detailed estimate will be ascertained in due course.
2	Whether loss / damage covered by insurance or not, including amount;	We would like to state that the Asset at the affected plant is adequately insured and the firm has already intimated the insurance company for the incident and insurance survey is expected to be conducted in due course.
3	Estimated impact on the production / operations, in case of strikes / lock outs;	Not Applicable
4	Factory /unit where the strike / lock out takes place including reasons for such strike	Not Applicable

MANUFACTURERS OF TVS BRAKE LININGS & CLUTCH FACINGS

Registered Office : Padi, Chennai - 600 050. India.

CIN : L34300TN1974PLC006703